

HABS
COLO,
16-DENV,
10A -

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Glenarm Branch, Denver Young Men's Christian Association HABS No. CO-45
(Glenarm Recreation Center)
501 28th Street
Denver
Denver County
Colorado

Documentation: 5 exterior photos (1981)
4 interior photos (1981)
16 data pages (1981)

Tom Masamori, Photographer; November 12, 1981

GLENARM RECREATION CENTER

CO-45-1	GENERAL VIEW OF SOUTHWEST FRONT
CO-45-2	SOUTHWEST FRONT AND SOUTHEAST SIDE
CO-45-3	NORTHEAST REAR
CO-45-4	DETAIL OF FRONT ENTRANCE
CO-45-5	DETAIL OF WINDOW ON SOUTHWEST FRONT
CO-45-6	BASEMENT HALLWAY AND STAIRS
CO-45-7	FIRST FLOOR NORTHEAST WING
CO-45-8	DETAIL OF SWIMMING POOL SLIDE END
CO-45-9	DETAIL OF OPPOSITE END OF SWIMMING POOL